

correspondencia
y dirigirse a los
Inspectores.



INSPECTORES:
R. CRAWFORD.
F. DE BERAZA.
J. C. KENDALL.
G. DIXON.

Lloyd's Register of Shipping.

OFICINA PRINCIPAL: FENCHURCH STREET, 71, LONDRES, E.C.3.

Calle de Ibañez de Bilbao No. 22,

4th Storey

(Apartado 286),

Bilbao, 13th November 1933.



Dear Sir:-

M.S. "CAMPERO" Bilbao Report N°8338

With reference to your letter of the 10th inst.
regarding the above we have to inform you that the proposed
working pressure for the high pressure air receivers is 75
atmospheres.

We are, Dear Sir,

Yours faithfully,

G. Dixon

For the Surveyors.

The Secretary

LONDON.



© 2021

Lloyd's Register
Foundation

013671- 013677-0074

Referred to the Chief
Referred to Mr. Spinks.

16 NOV 1933

The air receiver have
been experimentally tested
a pressure of 140 kgs instead
of 150 kgs as required by rule for
a working pressure of 150 kgs. Officially asked
submitted the Paris minimum ultimate
to state the minimum size of
strength of the steel for each
receiver.

ГОМОИ.

the Secretary


Dear Sir,

Enclosed.

Working pressure for the high pressure air receiver
regarding the above we have no information but that the
with reference to your letter of the 11th.

Dear Sir:-

W.3. "ГОМОИ" Вильям Роберт Билбро



Вильбро, 12th November 1933.

(Адреса 380)

4th Street

Call of Ipswich de Вильбро No. 33.

ОБЩИНЪ БУКОВЪТЪ БУКОВСКИ СЪВЕТЪ АТ. ГОДИНА Е.С.3.

Register of Shipping

ТЕЛЕФОНЪ 16189

2002.48



© 2021

Lloyd's Register
Foundation