

PT

21 JUN 1965

Ship's name "BALBUS"

Port

LGS

No. 4083

This tug is a C.S.H. case which was commenced in 6,62 and subsequently advanced. The Owners have not progressed the C.S.H. in accordance with the requirements - refer London letter dated 3.3.64.

The class is subject to set over stem bar being specially examined and dealt with as necessary next drydocking.

The LAGOS Surveyors report 9,64 tug examined in drydock and the majority of the outstanding C.S.H. requirements complied with.

To Complete C.S.H. the following items are outstanding:-

EXAMINATION OF:-


Dry space forward.  
Bosans store.  
Anchors and chain cables.  
Aux. steering gear.  
Hand pumps.

TESTING OF:-

Ballast tank fwd (p & s).  
Outboard O.F. tank (s.s).

In a letter dated 16.4.65 the Owners advised the tug was to be sold and requested her to be taken out of class.

The Class was withdrawn by the Committee 7.5.65.

  
18.6.65



© 2021

Lloyd's Register  
Foundation