

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

X

S/R 1



# Lloyd's Register of Shipping

RECEIVED

15 JUL 1952

And.....

United with the British Corporation Register

Rijksstraatweg 234 · Telefoon 44926

Haren (Gr.),..... 14th July, 1952.

S.

Re: M.S. "ZAMRUD".

Dear Sir,

With reference to your letter of the 1st instant I have to confirm that the length of the bridge is 31', as stated on the approved plan.

Bitumastic is only fitted in the water ballast tanks.

Yours faithfully,

The Secretary,  
LONDON.

GR 20.17.12/6.



© 2021

Lloyd's Register  
Foundation

013783 - 013793 - 0249

see letter 14/9/52.

CLASSIFICATION

14  
c  
YCC

For Slap Survivors (F. E. Folia) to make.  
Noted. [Signature]



© 2021

Lloyd's Register  
Foundation