

DISCLOSED SECTION
No. 8109

DISCLOSED SECTION
No. 810C

Ship's Name SS/MS

WELLINGTON

Gross tons *285*

Is there a rpt. 9?

Port *LON A*

Rpt. No. *164 631*

No. of visits

First date

Last date *15/7/6*

Interim Cert. issued & copy herewith?

Damage rpt. issued & copy herewith?

Last rpt. (H.Q. only)

Date of completing rpt.

Surveyed at, if different from Port above

Surveyed afloat and/or in D.D.

Last date of examination in D.D.

Has a Load Line Survey been held?

Freeboard Marks verified

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees

Damage fee

Expenses

S.A. fee

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

I have surveyed the above ship in accordance with the Rules for

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

I recommend that this ship remain as classed with/without fresh record of dry docking

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)


Date of Committee

FRIDAY 19 OCT 1962

Minute

Class withdrawn at Owners request
Write his

Surveyor to Lloyd's Register of Shipping



Mr. [Signature]
Lloyd's Register Foundation

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT



© 2021

Lloyd's Register
Foundation

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and fairied or replaced					
Fairied or repaired in place					

GENERAL COMMITTEE

Thursday,
8th November, 1966
Classing Committee's
decision confirmed.