

4-6-65

Ship's Name **SS/MS NAFPLION LR513737** Gross tons **1469**  
 Is there a rpt. 9? **Yes** Port **Aden** Rpt. No. **3994**  
 No. of visits **3** First date **23.5.65** Last date **25.5.65**  
 Interim Cert. issued & copy herewith? **Yes** Damage rpt. issued & copy herewith? **No** Last rpt. (H.Q. only) **PIR 11666**  
 Date of completing rpt. **27.5.65** Surveyed at, if different from Port above  
 Surveyed afloat and/or in D.D. **Afloat** Last date of examination in D.D. **-**  
 Has a Load Line Survey been held? **Part** Freeboard Marks verified **Yes**

State which additional Rpt. 8 is attached: ~~XXXX~~; (PS); (~~XXXXXXXXXX~~)

Survey fees **£30.** Damage fee *[Signature]* Expenses **Sh.10/-**

S.A. fee

I have surveyed the above ship in accordance with the Rules for Condition of Class.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

- 1/ Port side scupper valve No.3 tween deck and shell plating in way of now specially examined. Extended spindle control to valve connected and valve placed in open position. The shell plating in way would appear to have been recently renewed, no other defects were apparent and it is recommended that this item be deleted as a condition of Class.
- 2/ Port side Machinery casing locally doubled where thin and wasted. It is submitted this item be deleted as a condition of Class.
- 3/ Load Line marks now cut in, painted and verified. This item to delete as a condition of Class.

Short Term Load Line Certificate valid 6 months issued.

I recommend that this ship remain as classed ~~xxx~~ without fresh record of dry docking and without special condition regarding the port side scupper valve No.3 tween deck and shell plate in way, port side machinery casing and Load Line marks, but subject to any conditions at present attached to the ship's Class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

R. Gregory, *[Signature]*

Surveyor to Lloyd's Register of Shipping

Date of Committee

Minute

THURSDAY 22 JUL 1965

Deferred for comp SS (Equipment)  
DS 4.65 subject (h & m)  
ES 4.65 MBS (h.65)  
SPS 4.65

White (h) & re equip

Naft LS

FOR CHAIRMAN CLASSN. CITEE

22 JUL 1965

6 JUL 1965

013806-013811-0211 1/2

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

*dip. PIR 1965*

ALSO FOR
SPL FOR
TRO
SRL
POSTING
HEADER
CERT

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MX NAFPLION

S.S. ( ) Due

Port Aden

Rpt. No. 3994

	<u>Examined</u> & <u>condition</u>		<u>Examined</u> & <u>condition</u>
In dry dock from	-	* Air & sounding pipes	Not examined
.. .. to	-	Doublers under .. ..	Not examined
Shell plating	Not examined	Steering arrangements (main)	Not examined
Sternframe	Not examined	.. .. (aux)	Not examined
Rudder	Not examined	Windlass	Not examined
Was rudder lifted?	Not examined	Masts & rigging	Not examined
Plating, etc. in way of shell openings	Not examined	Hand pumps & suction	Not examined
Side scuttles & deadlights	Not examined	W.T. doors	Not examined
Overbd. scuppers & discharges	Not examined	Bulwarks, freeing ports, etc.	Not examined
F.P. spaces	Not examined		
Chain locker	Not examined	Summer freeboard as verified	1930 mm
A.P. spaces	Not examined		
Engine space	Not examined		
Boiler space	Not examined	<u>EQUIPMENT:</u>	
Under E. & B.	Not examined	Equipment letter	-
Coal bunker	Not examined	Fee ltr., if diff. from eqpt. ltr.	-
Tunnel & well	Not examined	Anchors: No. on board	-
Cement, asphalt, etc., on btm. shell	Not examined	State if ranged	-
Weather decks	Not examined	Length on board	-
* Casings	p.s. E.R. Good for SS	Mean dias. range from	- to
* Deckhouses	Not examined	Rule length	- Dia.
* Superstructures	Not examined	Mooring ropes	-
* Skylights	Not examined		
* Companionways	Not examined		
* Hatchways	Not examined		
* Ventilators	Not examined		
Other items:			

\* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

*R. Gregory*  
Surveyor to Lloyd's Register of Shipping

R. Gregory

0211 3/2