

Ship's name MUSWELL HILL

Port Piraeus

3 - MAR 1964

No. 10768

Last survey date 24.1.64

Class is subject to

- L. The electrical installation be repaired by 3.63, the electrical circuits to the cargo holds and forward stores being disconnected meantime.

ES due 7.61 (postponement SS until 3.63 approved) *now held*

MBS due 2.63 *now held.*

TS due 2.63 *now held.*

(LAID UP - SURVEYS OVERDUE 12.61)

S.P.S. due 12.64. *now held.*

S.R.L. item. Surveyor states the above item had been previously dealt with and was examined at this time and found in order. It is recommended that the above item may be deleted.

M/E engine L.P. cylinder upper steam part wicks found fractured and have been repaired by METALOCK. It is recommended that these repairs be specially examined and dealt with as necessary by 2.65.

Main condensed water - box repaired by fabricating a new branch piece and bolting it in place. It is recommended that these repairs be specially examined and dealt with as necessary by 2.65.

It is submitted that this vessel is eligible for THE

RECORDS E.S. 1.64, M.B.S. 1.64, S.P.S. 1.64, T.S. (CL) 11.63 without the above subject,

but subject as now recommended.

CERTIFICATE WRITTEN: