

COPY

013850-013858-0017

Ship's name MUSWELL HILL

Port Piraeus

No. 10768

Class is subject to

Last survey date 24.1.64

1. The electrical installation be repaired by 3.63, the electrical circuits to the cargo holds and forward stores being disconnected meantime.

ES due 7.61 (postponement SS until 3.63 approved) now held

MBS due 2.63 now held.

TS due 2.63 now held.

(LAID UP - SURVEYS OVERDUE 12.61)

S.P.S. due 12.64. now held.

S.R.L. item. Summary of States the above item had been previously dealt with and was examined at this time and found in order. It is recommended that the above item may be deleted.

M/E engine L.P. cylinder upper steam port valves found fractured and have been repaired by METALOCK. It is recommended that these repairs be specially examined and dealt with as necessary by 2.65.

Main condensed water-bore repaired by fabricating a new branch piece and bolting it in place. It is recommended that these repairs be specially examined and dealt with as necessary by 2.65.

It is submitted that this vessel is eligible for THE RECORDS 2.3.64, M.B.S. 2.3.64, T.S.(CL) 11.63 without

subject as now recommended.

© 2021 2.3.64.

Lloyd's Register Foundation