



Lloyd's Register of Shipping,

2/3, Piazza Cavour,

Genoa, 10th October, 1949.

AIR MAIL

RECEIVED

13 OCT 1949

Dear Sir,

S.S. "HALIGONIAN QUEEN".

The above vessel, classed with the B.C., now under survey, has been found without tunnel W.T. door.

Near the opening leading from Engine Room to the tunnel, is now fitted a plate which can be bolted on the opening.

We would be very glad to have instructions how the case has to be dealt with.

Yours faithfully,

PRINCIPAL SURVEYOR FOR ITALY

The Secretary,
London.



© 2021

Lloyd's Register
Foundation

013850 - 013858 - 0108

Referred to Mr. Perris.

Sp
Urgent.

Submitted Surveyor be advised what this
arrangement cannot be accepted and what
a watertight door obstructs further independence with
the Rules or the plate. permanently made to the
breakdown. it being assumed that a tunnel escape

LONDON.
The Secretary.

BY MINISTRY OF DEFENCE FOR MR. PERRIS

London 12/11/29

the case has to be dealt with.

We would be very glad to have information how
the opening.

tunnel, is now fitted a plate which can be bolted on

next the opening leading from engine room to the
navigating bridge, has been found without tunnel W.P. door.

The above vessel, engaged with the B.C., now

S.A. "NAVIGATIONAL SERVICE".

Dear Sir,

RECEIVED

GENOY

10th October 1929.

THE MAIL

1/3

RECEIVED

Office of the Registrar of Shipping

© 2021

Lloyd's Register
Foundation