

# LLOYD'S REGISTER OF SHIPPING

FOUNDED 1760

RE-CONSTITUTED 1834

## LLOYD'S MACHINERY CERTIFICATE (LMC)

This is to Certify that the Machinery of the

Motorship "MOANA ROA"

2893 Tons, of Auckland

has been Specially Surveyed by the Surveyors to this Society during construction at Sunderland

and was reported to be on the 16th August, 1960 at Grangemouth in good working condition.

The Record  LMC has been made in the Register Book, subject to Periodical Surveys as required by the Rules.

### PARTICULARS

|  |   |                                       |
|--|---|---------------------------------------|
| Description of Machinery                           | 2 Oil Engines<br>2 Stroke Cycle Single Acting<br>to two screwshafts |                                       |
| Makers of Main Engines                             | George Clark (Sunderland) Ltd.,                                     |                                       |
| Makers of Main Boilers                             | -   |                                       |
| Approved pressure of Main Boilers                  | -   | lb. per square inch saturated steam   |
| Steam Temperature                                  | -   | lb. per square inch superheated steam |
| Approved pressure of Aux./Donkey Boilers           | -   | lb. per square inch                   |
| Approved pressure of Steam Heated Steam Generators | -   | lb. per square inch                   |
| Approved total                                     | B.H.P. 3080   | 250 r.p.m. of Engine                  |
|  | S.H.P. -  | 250 r.p.m. of Propeller               |

Witness my hand


*W. J. Ferguson*  
Secretary

*Herbert Kelly*  
Chairman

71, Fenchurch Street, London, E.C.3. 22nd September, 1960.

This Certificate is issued upon the terms of the Rules and Regulations of the Society to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register  
Foundation