


COPY

# LLOYD'S REGISTER OF SHIPPING



Port London

7th November, 1957.

This is to Certify that I have

Part  
Surveyed the **Boiler** and Machinery of the S.S. "COMMONITY"  
469 tons gross of London on 2nd November, 1957, whilst the ship  
was on a hard at Greenwich on account of damage to the screwshaft  
stated sustained whilst the ship was on passage from Goole to  
London on 23rd October, 1957,

and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report stating that all  
recommendations made by me in connection therewith have  
been carried out to my satisfaction, and that I have

Recommended that the record of Shellshaft survey Oil  
 gland 11-57,

be made in the Register Book in the case of this vessel when  
the survey has been completed.

Parts now examined :-

Propeller, external fastenings screwshaft and oil gland.

Engineer Surveyor to Lloyd's Register

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."