

Ship's name

"AWATA MARU"

Port Kobe

No. 19218

BEFORE THIS CASE receives the consideration of the Committee the Surveyors should be advised that the Yokohama Surveyors in 12.67 recommended a bower anchor being supplied at the earliest opportunity and the first 2 lengths of chain cable (s) being re-tested at the next drydocking. Their comments are requested.

See letter 25-3-68

15/3/68

183



© 2021

Lloyd's Register
Foundation