

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760.

RE-CONSTITUTED 1834.

CERTIFICATE FOR MACHINERY.

This is to Certify that the Machinery of the

"Steel Screw Motorship Nordhem" now named "Scandus"
British *Swedish*
1042 || 1046 Tons, of Stockholm

has been Specially Surveyed by the Surveyors to this Society during construction at Stockholm and was reported to be on the 20th July 1949 at Norwoking & in July 1951 at Manchester in good, efficient, and safe working condition.

The Record \times LMC 749 (Lloyd's Machinery Certificate) has been made in the Register Book, subject to Periodical Surveys as required by the Rules.
Strengthened for Navigation in Ice.

The Notation DB 178 lb (Donkey Boiler) has also been made in the Register Book.

PARTICULARS OF ENGINES.

Description.	When Made.	Name and Address of Makers.	CYLINDERS.		Length of Stroke.
			No.	Dia.	
<u>Oil Engine</u> <u>Two Stroke Cycle</u> <u>Single Acting</u>	<u>1949</u>	<u>A. B. Atlas Diesel</u> <u>Stockholm</u>	<u>5</u>	<u>13$\frac{3}{8}$"</u>	<u>22$\frac{1}{16}$"</u>

The engines must not be run continuously between 55 and 75 R.P.M. & between 130 and 150 R.P.M., and the blower shafting to be examined after a period of service not exceeding twelve months.

Witness my hand,


P. E. Clement
Secretary.

R. H. A. A. A. A.
Chairman.

71, Fenchurch Street, London, E.C.3. 16th August, 1951.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation