

LLOYD'S REGISTER OF SHIPPING

Port BILBAODate 1st February, 1965

we

This is to Certify that I have

surveyed the **M.S. "BALKAN"** **7372 Gross tons** of **Varna**
 on the 23rd January 1965 and subsequently whilst the vessel
 lay afloat at Santurce and Pasajes on account of damage stated
 due to Ranging against wharf at Santurce on the 18th January
 1965 during strong winds.

and that ~~I am~~ ^{we are} transmitting to the Committee of Lloyd's Register of
 Shipping, London, a report, stating that all repairs recommended by
~~me~~ have been completed to ~~my~~ ^{our} satisfaction, also that ~~I am~~ ^{we are}
 recommending that she be continued as now classed without fresh
 record of drydocking subject to N^o 5 plate etc. in 1st below
 mainsheer (s.s.a.) in way N^o 2 Hold and starboard side bilge
 plating together with framing etc., in way of N^o 2 Hold, Deep
 Tank and Machinery Space be examined and dealt with as found
 necessary in drydock at Antwerp to which port the vessel is
 now proceeding direct and to compliance with all outstanding
 recommendations previously made by the Society's Surveyors.

[Signature]
 Surveyor to Lloyd's Register of Shipping

Sgd.: L.D. Phillip for J.M. Ruiz
 and self.

KEY TO ABBREVIATIONS

AS Annual Survey
 BiS Biennial Survey
 DS Docking Survey
 NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
 SS(Dr) Hull Special Survey (Drilling)
 SS(M) Hull Special Survey (Modified)
 CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021

Lloyd's Register
Foundation

014068-046076-0242