

Ship's Name **SS/MS "BALI MARINER". (ex "Ricardo").** IR 508395.
Gross tons **6491.** Port of Registry **Panama.** Port **HONG KONG.**

Date of build Is there a rpt. 8? **Yes.** Rpt. No. **20001.**

No. of visits First date Last date
Interim Cert. issued & copy herewith? Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)

Date of completing rpt. Surveyed at, if different from Port above

Is a rpt. 9A attached? **Yes.** MN Nature of survey

Survey fees Damage fee Expenses

See Rpt. 9A.

S.A. fee

DOCKING

Propeller **Good.** Sea connections **Good.** Oil gland

Fastenings **Good.** Wear down of stern bush (if relined, state clearance before and after) **P.: 5/32"**

Has screw/~~tube~~ shaft been drawn? **No.** Date of examn. **S.: 1/8".**

Has shaft been changed? Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves { Sat
adjusted to { Spt

Boiler securing arrangements

Main economisers

Steam heated steam generators

Forced circulating pumps

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Exhaust gas heated economisers and their safety valves

Steam generator safety valves adjusted to

Funnel

Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of

See Rpt. 9A.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

N. Stephenson
Surveyor to Lloyd's Register of Shipping

TUESDAY 8 MAR 1966

014077- 014082- 0120

ALSO FOR

SPL FOR

TRO

NOTED BY

SR

POSTING

HEADER

CERT

All part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is