

EA

14 MAY 1964

Ship's name "DAGMAR"

Port

PNG

No 3817

Last survey date 10.4.64.

Class is subject to

one length of chain cable being supplied
at the earliest opportunity.

S.R.L. Appendix (~~xxxxxxx~~ none)

Nature of present survey (afloat and ~~in drydock~~)

Loss of port bower anchor and 4 lengths
of chain cable.


Recommendation

SUBJECT as above and to a bower anchor and 4 lengths
of chain cable being supplied at the earliest
opportunity.

As Now Subject.

Total 5 lengths of CC.

C.S.S. Records Dept.
to note.



Lloyd's Register
Foundation

DAGMAR
13.5.64

014077-014082-0169