

1960
SERVICES

11 13th, 1960

Steel "THORDOC"
Built at Hull By whom Earle's Company When 1927 5
Owners N. M. Paterson & Sons Limited
53 Managers Port belonging to Fort William
At or in Dry Dock? Afloat Name of Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. Port

REPAIRS, OR EXAMINATION AS PER RULE FOR
LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS ^x Great Lakes & River St. Lawrence Service. Lake S. S. 6/56 A. S. 4/59 D. S. 6/56	MBS ^x ES 4/54 MBS 2/59 TS (C.L.) 5/56 SPS 1/55

ITEMS EXAMINED AND CONDITION FOUND, ETC.	
Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	-do-
Tween decks.	-
Deck & deck erections.	Good
Machinery Space.	-do-
Under Engines & Boilers.	-do-
Masts, Rigging & Outfit.	-do-
Windlass & Hawse Pipes.	-do-
Air & Sounding Pipes with closing appliances.	-do-
Pumps and Pumping arrangements outside machinery space.	-do-
Steering arrangements including gear.	-do-
W.T. Doors & Sluice valves.	-do-
Ventilator coamings with their closing appliances.	-do-
Hatchway coamings with their closing appliances.	-do-
Casings, companionways and their closing appliances.	-do-
Superstructure bulkheads with their closing appliances.	-do-
Guard rails & freeing ports.	-do-
Overboard discharges, also ash chutes & other shell openings.	-do-

	EXAMINED	TESTED	CONDITION
Peaks	Yes	No	Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams			
Pump Rooms			
(Tankers)			
Has a Load Line Annual Survey been held?	Yes		
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No		

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, I,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,60

Survey Fee \$ 36.00
U.S.S.A. 4.00
Special Damage or Repair Fee (if any) \$ 30.00
Travelling Expenses \$ 5.00
Second Surveyor's Fee (if any) \$
Committee's Minute MONDAY - 9 MAY 1960
Character Assigned AS 4. 60
MBS 2. 60

Fees applied for, APR 20 1960

Thetimer
Surveyor to Lloyd's Register of Shipping.
(D. McKINNON)