

2m.11.33.

2

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

LURLINE

Report

5 Fo.

No. 8176

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/3/92.)

1st 5.5 No. 2

SURVEY

commenced
~~PARTLY HELD.~~

✓ additional stiffening
in wing fuel oil bunkers

When due

12 40

When proposed to be completed

not stated.

Portion of Survey held, &c.,

To complete the survey & see Report.

Noted.

ACS
8.3.40



© 2021

Lloyd's Register
Foundation

014159-014165-0027