

Can each boiler be worked separately

~~Engine~~ No. 4607. Made by Messrs Yates & Thorne  
 or Controller of Merchant Shipping  
 at Messrs Beaver Docking & Co's Mch. Report No. 4447  
 Bradford

It is submitted that further action in the case is  
 unnecessary until this ~~boiler~~ <sup>engine</sup> is ~~not intended for~~ fitted on  
 a  
 classed vessel.

R.M.

Date

18/11/19

Entered in ~~"Unclassed"~~ Boiler Book.

5c.8.19.

014159 - 014165 - 0132

material

Description of longitudinal joint

Pitch of rivets

Working pressure of shell by rules

Cover plates

Thickness

