

2 JAN 1964

Ship's Name ~~SS~~MS "GLANMIRE" ex "LAIRDSBANK" Gross tons

Is there a rpt. 8? Port Belfast Rpt. No. 1436

No. of visits First date Last date

Interim Cert. issued & copy herewith? Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)

Date of completing rpt. 26.12.63. Surveyed at, if different from Port above

Is a rpt. 9A attached? Yes MN Nature of survey

Survey fees Damage fee Expenses

S.A. fee

DOCKING

Propellers P. & S. Good Sea connections Good Oil gland P (externally) Good S Good

Fastenings Good Wear down of stern bush (S) 0.074"

Has screw/shaft been drawn? ~~Yes~~ Starboard Yes - Good Date of examn. 31.10.63.

Has shaft been changed? No Has shaft now fitted been previously used? -

Has shaft now examined/fitted a continuous liner? No Approved oil gland? Yes

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings; doors and fastenings

Safety valves adjusted to { Sat Spt

Boiler securing arrangements

Main economisers

Exhaust gas heated economisers

Steam heated steam generators

Steam generator safety valves adjusted to

Forced circulating pumps

Funnel

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

Surveyor to Lloyd's Register of Shipping (P. Couch & R.I. Murchison)

MONDAY 27 JAN 1964

See Rpt 9A

ALSO FOR
SPL FOR
TRO
SRL /
POSTING
HEADER
CERT



014242-014252-0163

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark thus should be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?


ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW XXXXX	135
a Generators		l Generators & governors	Good
b Exciters			
c Air coolers		m Motors	Good
d Motors			
e Air coolers		n Switchboards & fittings	Good
f Control gear cables, etc.		o Circuit breakers	Good
g Insulation resistance		p Cables	Good
h Insulating oil test		q Insulation resistance	Good
i Overspeed governors		r Steering gear generators & motors	Good
j Magnetic couplings		s Navigation light indicators	Good
k Air gap			

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

ELECTRICAL REPAIRS:- SEE REPORT 9A.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Lloyd's Register
Foundation