

Received from Chief Ship Surveyor

6 SEP 1955

NAME

"V I D A"

REPORT

Spt.

No. 1906

Existing Conditions of Class:

NONE.

Assignment of Class (B) (~~As before~~ None)

Result of Present Survey: (Afloat ~~and in dry dock~~)

Damage (contact) involving stem and stem plating.

Recommendation:

SUBJECT to permanent repairs to stem and stem plating, etc. as necessary next drydocking. *a.*

As Now. Subject.



© 2024 *PL*  
5-9-55

Lloyd's Register  
Foundation  
014335-014348-0162