

17 SEP 1953

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 4 AUG 1953

SHIP'S NAME "MEISEI MARU" REPORT Sunk. No. 183.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

There are no conditions or endorsements of class.


The Shimonoseki Surveyors report (3.53) the ship placed in dry dock and bottom coated.

On account of wear & tear, repairs effected to shell and inner bottom plating, frames, shell rivets etc.

The ship has now been converted to a "Shelter Decker" and a third deck fitted in nos. 1 & 2 holds; also additional deep tanks for the carriage of oil fuel and fresh water have been fitted all in accordance with the Rules and approved plans attached - (See also memo dated 30.12.52).

The equipment at present carried (letter Z) is suitable for the increased numeral - (refer Kobe letter dated 18.12.52).

The nos. 1 & 2 holds, no. 2 lower tween deck and the upper tween deck between frames 89-110 have been insulated for the carriage of frozen fish but the Owners do not require classification for these spaces nor for the refrigeration machinery.

It is SUBMITTED the class be amended to +100 A1 "With freeboard" with record of docking 3.53. +100 A1 "With freeboard"
3.53 Sunk.

© 2021

P.T.O.

Lloyd's Register
Foundation

Amend R. B.

From: +100 A1;

1 Dk.;

To: +100 A1 'With freeboard'; 1 Dk. & Sh. Dk., 3rd dk. fwd. of mch. space; 6 BH
to 2nd Dk. 6 BH

Delete from R. B.

P. 35' B 261' F 33'

Insert in R. B.

D.T's amids. & a O.F.

Wing tanks in mch. space F.W.

Converted to Shelter Decker '53.

Freeboard Surveyors to note.

G.O.

29.7.53.



© 2021

Lloyd's Register
Foundation

are requested not to write on or below the space for Committee's Minutes.

Now
The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Discharge Committee.
The recommendations of the Chief Ship Surveyor are desired on this case for the consideration of the Discharge Committee.
If so, is the Report sent now, or when will it be sent?
RE
Deck
Caulk
Coam
Beam
Outs
"
Fram
Rever
Long
Trans
Floor
Keels
String
Inner
Have
Have
G
10
Surv
Spec
Tra