

COPY.

# Lloyd's Register of Shipping.



Port SAN FRANCISCO

10th March 1950.

9507

**This is to Certify** *that I have*

Surveyed the S. S. "MONTEREY", 18,170 tons gross of San Francisco,

whilst afloat at U. S. Maritime Commission Shipyard, Alameda, Cal.

for damage to port shell plating and internal fittings in way of

No. 10 Deep fuel tank

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report, stating that all repairs

recommended by me have been completed to my satisfaction, and

that I have Recommended that she be retained as now classed

without fresh record of survey subject to repairs to shell plating,

No. 10 Port fuel oil tank being carried out before

vessel is recommissioned

being fit ~~to~~ for "Laid up" condition


(Signed) E. MARLBOROUGH

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in  
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of  
its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.) 5M-3-48

PRINTED  
IN  
U.S.A.



Lloyd's Register  
Foundation

014513-014530-0040