

Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 9th April, 1926.



LLOYD'S REGISTER

Recd. 10 APR 1926

Ans'd. 15

LONDON

Dear Sir,

In reply to your letter of the 7th inst, regarding the omission of automatic indicators for the navigation lamps in the Electrical Installation of the s.s. "TOTARA", Hull Report. No. 36940, I beg to inform you that on enquiring if it was intended to fit these indicators, the contractors stated that these fittings were not specified, and it was not their usual practice to fit them in vessels of this type. I then referred them to the Rules, and informed them that if they wished to omit the indicators it would be necessary for them to obtain the permission of the Owners, whereupon the case would be submitted for the consideration of the Committee.

The Contractors appear to have written to the Owners on the subject, but up to the time of completion and the vessel sailing, no reply had been received. The omission of the indicators was pointed out to the Owners representative and no objection was raised.

No arrangements have been made for the indicators to be fitted.

I am, Dear Sir,

Yours faithfully,

P. Fitzgerald

The Secretary,
London

014513-014530-0347

© 2021

Lloyd's Register
Foundation

Referred to the Chief Engineer Surveyor.

ram ad
10 APR 1926

For Mr. Wayne
to note

Shl
RA



© 2021
Lloyd's Register
Foundation

OFFICIAL COPY

LONDON