

Lloyd's Register of Shipping

810 Merchants National Bank Bldg.

"RAPHAEL SEMMES"

With reference to the Mobile Surveyor's letter of 12.5.53, IT IS SUBMITTED the Philadelphia Surveyors be informed that if documentary evidence of the adjustment of the safety valves by the American Bureau and the United States' Coast Guard in October, 1952 can be produced, this could be accepted as completion of the Boiler Survey. Alternatively, the Surveyors should state what arrangements have now been made for the survey to be completed.

The Secretary
Lloyd's Register of Shipping
25, Abchurch Lane
London, E.C. 4

llh

27.5.53.

L.F.

Dear Sir,

"RAPHAEL SEMMES"

In reply to your letter of the 7th instant, the Surveyors of the above vessel would inform us that the safety valves of the boiler were adjusted by the American Bureau of the Coast Guard in October 1952, at Philadelphia. The Surveyors are unable to accept the Society's statement that the boiler was not surveyed at that time.

The Surveyors would also inform you that the safety valves of the boiler were adjusted by the American Bureau of the Coast Guard in October 1952, at Philadelphia. The Surveyors are unable to accept the Society's statement that the boiler was not surveyed at that time.

The Surveyors would also inform you that the safety valves of the boiler were adjusted by the American Bureau of the Coast Guard in October 1952, at Philadelphia. The Surveyors are unable to accept the Society's statement that the boiler was not surveyed at that time.



© 2021

Lloyd's Register
Foundation

014631-014641-0278

Yours faithfully,

[Signature]