

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME Raphael Semmes. REPORT Bal No. 9872

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey Docking. When due.....

Noted.
Subject to wavy bottom plating
being specially examined next
drydocking.


2-53 Bal subjed.

ARB

9. 4. 53 JWA

NOTE. Ship's name appears on
list attached to Circular 1934.
American built - all welded type.

And
C.S.S. Records Dept.
to note: measurement
of wavy bottom (see
also Mob 2591).



© 2021 Noted JWA

Lloyd's Register Foundation
to note