

BRITISH CORPORATION

nt to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME PLATANO

N.Os. 7098

REPORT N.Os. No. 7104

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

( TYPE 3 No. SPECIAL SURVEY PARTLY HELD. N.Os. 6.49) Damage to Equipment.  
 when due 5.51 When proposed to be completed *as indicated*

tion of Survey held, &c. Examination of No. 2 D.B. tank top plating.


NOTED

Subject to 30 fathoms of chain cable being supplied by March 1950.


C.S.S. Records Dept.

to note.

N.Os. 7098



*BM.*  
 18.11.49.



© 2021

Lloyd's Register  
 Foundation

014642-014653-0049