

COPY.

# Lloyd's Register of Shipping



Port NEW ORLEANS, LOUISIANA

29 September, 1949

**This is to Certify** that I have

Surveyed the <sup>Port After</sup> Boiler ~~and Machinery~~ of the Steel Screw Steamer

"PLATANO" (BC) 5949 tons gross of Tela, Honduras, afloat at this port

for examination of repairs to the combustion chamber of the port lower furnace

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the record of MBS\* 5,47

remain ~~made~~ in the Register Book in the case of this vessel.

*J. A. Laing*  
Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."