

COPY.

# Lloyd's Register of Shipping



Port NEW ORLEANS, LOUISIANA

19 September, 1949

**This is to Certify that I have**

*Surveyed the Steel Screw Steamer "PLATANO" (BC) 5949 tons gross of Tela, Honduras, afloat at this port for examination of the port anchor chain on account of damage stated sustained while heaving in the port anchor leaving Tela, Honduras on 15 September, 1949 about 8:30 a.m. and repairs and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued as classed without fresh record of survey subject to 30 fathoms of stud link chain of the proper size being placed on board and connected up to the port anchor as soon as obtained and not later than six months from this date being fit to carry dry and perishable cargoes.*

*J. A. Laing*  
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.) 5M 6-49

PRINTED  
IN  
U.S.A.

014642-014653-0054

Lloyd's Register  
Foundation