

COPY.

24 MAY 1947

No 14938

# Lloyd's Register of Shipping.



Port Reykjavik.

8th. of December 1946

This is to Certify that

M. E. Jensen.

the undersigned Surveyor to this Society did at the request of the Owner of the S/Tr. "Vaxi" of Hafnarfirði, Iceland, examine a damage on the said vessel sustained, according to the ships log, on the 4th. of August during fishing. The vessel was placed on Slipway, carefully examined, and the following damages found and repaired. Stb. side.

Plate B.1. slightly indented, faired in place.

Plate B.10. badly indented, renewed.

Plate D.11. badly indented, renewed.

Plate B.10. badly indented, renewed.

Aft. 12 m. of D. banding on shipside badly bent and broken, renewed.

All the repairs were carried out under my supervision and to my satisfaction.

*M. E. Jensen.*

Fee 21-0-0.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."