

On December, 1951.

COPY

LLOYD'S REGISTER OF SHIPPING,

HONG KONG.

17th December, 1951.

Dear Sir,

With reference to your letter of 15th November, 1951 enquiring whether there is any change in the circumstances relating to the dermentioned vessels, we beg to report as under:-

- HING MEN") Owners state that the circumstances of these two
UEI MEN") vessels remain unchanged.
- HEUNG KUNG") Owners' Hong Kong Office state they have no
HUN YU") definite news of these two ships and do not expect
them to call at this Port in the near future.
- HEUNG-CHUN") Owners state that the circumstances of these two
-LAN") vessels remain unchanged.
- HUNG LAI") Owners state that the Classification of these two
HUNG TUNG") vessels have been transferred to A.B. in June this
year.
- Redger
HIEN SHE" - We understand the circumstances relating to this
vessel remain unchanged.
- AN LIEN" - Letter was written to Owners in Formosa last month,
but no reply has yet been received.

SSS "KAO HSIUNG"

Regarding the worn chain cable of this vessel (our Report N°10507) Owners state they have instructed their Hong Kong Agents to seek for the replacement and will let us know when the suitable size of cable has been procured.



Copied for Freeboard

© 2021
Lloyd's Register
Foundation

014771-014776-0086

The reviewed in
cross time

R.H.



© 2021

Lloyd's Register
Foundation