

550'-0" B.P. x 70' (MLD) x 40'-6" (MLD)

17 DEC 1942

Modifications shown in blue not
fitted in No 1711.

C. H. Dean
8/4/46.

Special attention to be paid to
maintenance of strength at break
Sketch to be submitted.

Upper deck stringer and plating 10" or $\frac{1}{2}$ length to .58' and .46' respectively at ends.
Stringer increased at Poop front and Bridge end to 1.17"
Deck welded direct to shell.

Deck plating to be suitably increased where total breadth of openings exceeds 7'-8" in any transverse space.


J. & A. HUNTER, & WIGHAM RICHARDSON
SHIPBUILDERS & ENGINEERS
DATE 4 12 42
N° 22
WALLSEND SHIPYARD
WALLSEND-ON-TYNE

ISSUE NO 2
5-12-42

W.S.
17. 12. 42
© 2021
Lloyd's Register
014784 014793-0003
Foundation

SWAN HUNTER & WIGHAM
RICHARDSON LTD.

SHIP No. 1689

"OLNA" 

NEWCASTLE ON TYNE

Report No.

Profile + Decks.

SHIP No. 1711

"Helicina"

NEWCASTLE ON TYNE

Report No. 104096

4



© 2021

Lloyd's Register
Foundation

014 784 - 014 743 - 0003