

A new form should be prepared if any alterations that affect the freeboard have been made. If no such alterations have been made, the Surveyor should endorse the form on this side with his signature and the date.

Poop

~~inches~~
Projection fwd.

$$\frac{10 \times 30}{70}$$

=

146.83

$$\frac{4.29}{151.12}$$

overhang

$$\begin{array}{r} 10.00 \\ - 4.29 \\ \hline 5.71 \end{array}$$

Bridge

$$\frac{2}{3} \times 4.75 =$$

$$\begin{array}{r} 50.52 \\ 3.17 \\ \hline \end{array}$$

53.69

$$53.69$$

$$\frac{4.25 \times 21}{70}$$

$$\begin{array}{r} 1.27 \\ 54.96 \\ \hline \end{array}$$

$$\begin{array}{r} 4.25 \\ 1.27 \\ \hline 2.98 \end{array}$$

Trade of ship

Admiralty Service

Names of sister ships

✓

Builder's name and yard number

Swan Hunter Wigham Richardson, Wallsend. 1689.

Owners

Admiralty.

Fee £

20 to charged with F.E.

128



© 2021

Lloyd's Register
Foundation