

TELEGRAMS: REGISTER, SHIMONOSEKI  
TELEPHONE: SHIMONOSEKI 2938



# Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)

RECEIVED  
Nokyo Building, 161, Buzenda-cho  
Shimonoseki, Japan

12 OCT 1954

Shimonoseki 21st September, 1954.

Reference  
Classn(S)

Dear Sir,

## 1st Entry Report Shimonoseki 330 "AKI MARU"

We have to acknowledge the receipt of your Classn(S) letter of the 16th Sept., 1954 concerning our Hull Report No. 330 on the M.V. "AKI MARU" and in reply to advise as follows:-

1. Length of the bridge and forecastle as stated in our report should be 200 ft. and 41 ft. respectively.
2. The thickness at the fore end of the side plating of the shell should be 16 m.m. above L.W.L.
3. The thickness of plating abreast the deck openings in way of the wells in 26 m.m.
4. Equipments;

### Particulars of Drop Test of Cast Steel Anchors.

1st Bower	54	cwts	-	0	qr.	-	3	lb.	T.N. Y-4820	18-8-53
2nd "	53	"	-	3	"	-	19	"	T.N. Y-4821	24-8-53
3rd "	54	"	-	0	"	-	3	"	T.N. Y-4819	18-8-53

### Hawsers and Warps

Now placed on board as per rules requirement thus,  
Hawsers, 2 coils Manila @100 fms of 8 3/4 circ.  
Warps, 2 coils Manila @100 fms of 8 circ.

Regretting the erros made in our Report,

Yours faithfully,

*Hamada*  
For the Surveyors.

The Secretary  
LONDON.

c.c. The Surveyors,  
KOBE.



© 2021

Lloyd's Register  
Foundation

014794-014805-084



CLASSIFICATION

H

*[Handwritten signature]*



© 2021

Lloyd's Register  
Foundation

