

LT

REGISTER COLOMBO (CEYLON)

(16 2 65)

SUDBURY HILL DUE TRINCOMALEE NOW FOR VERIFICATION REPAIRS TO GUARD RAILS  
AND EXAMINATION NO. 2 DB AIR PIPE STARBOARD <sup>AW</sup> ~~HOSE~~ PIPE SIDE SHELL PLATING  
WAY PORT <sup>AW</sup> ~~HOSE~~ PIPE ALSO STARBOARD GYPSY AND RENEWAL WINDLASS STARBOARD  
SIDE OUTBOARD MAIN BRACKET GIVE CASE ATTENTION

COMMITTEE.



© 2021

Lloyd's Register  
Foundation

014806-014814-0203