

29 SEP 1964

Ship's name

"SUDBURY HILL"

Port

Mch

No.

20992

GB Class is subject to

NONE

Last survey date

14.8.64.

S.R.L. Appendix (as before of ~~XXXXXXX~~ ~~XXXXXXX~~)

Nature of present survey (~~XXXXXXX~~ ~~XXXXXXX~~ in drydock)

Docking: Wear and tear repairs.

Recommendation


SUBMITTED record of 'DS 8,64' be assigned, subject to rudder bottom bush being specially examined and dealt with as necessary next drydocking.

DS 8,64 Subject

IN S.R.L. APPENDIX.

Shell plate G.16 etc. (s.s. from aft) slightly set in.

Shell plate H.7 (p.s.a) slightly indented.



Lloyd's Register
Foundation

Signature
16/9/64