

# MONTREAL OFFICE

Name:- LUBROLAKE

Report No. 18040

Nature of Survey:- Damage Survey

Damage stated sustained through ice on the 13th April, 1965.

The following remains to complete the survey:- The alignment of the starboard rudder stock and bearings to be further examined and dealt with as necessary at the forthcoming winter lay-up and the starboard propeller examined and dealt with as found necessary at the next dry docking; the engine room floors to be examined, deck beams in cargo tanks to be dealt with and Renewal Freeboard Survey held.

Recommendations:-

The Vessel appears eligible to remain as classed <sup>with</sup> without fresh record of DS 10.66 now and notation of Lake SS (With date) when the Survey has been completed as above.

014873 - 014886 - 0209

25th January, 1967

© 2021  
Lloyd's Register  
Foundation