

Lloyd's Register of Shipping.

(Report on Vessel No.)

Port Newcastle

The words FORGINGS or CASTINGS, IRON or STEEL, should be struck out as may be required.

No.

SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs E Jopling & Co Ltd of Sunderland for the Vessel No., being built by MV Aquila II of have been inspected by me as set forth below and found to be, so far as can be seen, Sound

Mark on Forgings or Castings.

Lloyd's
No. 8540
JD 8541
11.10.35

J Dale
Tiller & Quadrant Sunderland
11.10.35

	STERN FRAME.	RUDER FRAME.	STEM.
Material* ...	/	<u>Cast-Steel</u>	/
How made ...		<u>Electric furnace</u>	
If annealed ...		<u>yes</u>	
Dimensions ...		<u>Pattern</u>	
Progress on Inspection ...		<u>Cleaning & Testing</u>	
Date when Inspected ...		<u>11.10.35</u>	
CASTINGS.			
Tests on Standard Test Pieces.			
Tensile Test—		<u>32.5 - 31.0</u>	
Tons per square inch ...		<u>32% - 33%</u>	
Extension per cent. ...		<u>120 - 120</u>	
Cold Bending Test—		<u>6 ft</u>	
Angle before fracture ...		<u>yes</u>	
Drop Test—			
Height from ground ...			
Hammering Test—			
If made according to Rules and found satisfactory ...			


SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ Monthly

To be paid at

Total Weight 13.3.0

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.
5m.1.30. T. 014899 - 014911 - 0140



10105 - March 2017
to 10107

10105
10106
10107

EXTREMELY STRONG

THE MIDDLE

10105
10106
10107
10108
10109
10110
10111

AGUILA II

Aguila II



© 2021

Lloyd's Register
Foundation