

1500,10,40.

Cook, Welton & Gemmell Ltd., Beverley. Yard No. 676.

F.E.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "INCHCOLM" Rpt. Hull No. 51295

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2250

Depth "d" -

2nd Long. No. 6390

Proportions = $\frac{L}{D}$ 10.0

Framing Angle framing as approved

Sheerstrake As approved

This is a sister vessel to the "HAMLET" etc.


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A- "Stm Trawler" "For Government Service"

FK, 7 BH

F 27'

O.L. 164.5'

Note: For coating of bottom see sister vessels.

1.C.D.
19.8.41.

© 2021

Lloyd's Register
Foundation

014974-014983-0337

Solid Are Frame and Reversed Frame }
joggled ?

Bridge Deck, Angle, E or F