

4 OCT 1950

Lloyd's Register of Shipping,

Hedjuff,

Aden, 16th September 1950



Dear Sir,

M.S. "Stratton Croft"

With reference to your "S" dated 1st February 1950.

This vessel was docked here for 24 hrs for scraping and cleaning, I took this opportunity of visiting accompanied by the owner, He seemed very reluctant at classification as the Special survey could not be completed in the 24 hrs and has decided to wait until next docking.

During the brief examination it was found that there were several very deep local indentations and one section extending over six frames on the port side where the side is set in, the frames being kinked.

I remain Dear Sir,

Yours faithfully,

Surveyor.

Clerk to the
Classification Committee.



© 2021

Lloyd's Register
Foundation

0150 22-015025-0014

REGISTRATION

sb

CLASSIFICATION

R

Handwritten initials

Classification Committee.
Clerk to the

Dear Sir,

Handwritten signature
Yours faithfully,
[Signature]

I remain Dear Sir,

the issues being linked.

over six items on the board where the size is set up.
Several very good local improvements and one section extending
during the pilot examination it was found that there were
many next working.

could not be completed in the 24 hrs and was decided to wait

He seemed very reluctant to circulate as the speaker advised

I took the opportunity of visiting accompanied by the owner.

The vessel was docked here for 24 hrs for working and cleaning.

With reference to your "2" dated 1st February 1980.

"13702 not working". S.M.

Dear Sir,

© 2021

Lloyd's Register
Foundation

RECEIVED
10 OCT 1980

RECEIVED
OCCUPATIONAL
LIFE
INSURANCE
DIVISION

1980 redmages 1820

Hebuh,

Handwritten text: *Handwritten text*

1980 130 A

TELEPHONE NO. 020 746 1718

020 746 1718