

Received from Chief Ship Surveyor

17 APR 1953

SHIP'S NAME

"BALTICIA"

REPORT

Cpn.

No. 14175

Standing Conditions of Class:

Subject to deck in way of bridge house being specially examined next drydocking and dealt with as necessary by the Special Survey

Reformulation of Class (B) (~~as before or~~ None)

Scope of Present Survey: (Afloat and in dry dock)

Docking, grounding damage repairs, W+I. repairs, examⁿ of above also fitting of cargo battens.


Recommendation:

Submitted record of docking 3.53 be assigned subject as above.

3.53 Abg. subject

Delete from R. B.

"Cargo battens not fitted."



© 2021

Lloyd's Register
Foundation

015039-015053-0298