

Baltic

~~John S. Danyorn~~

11

5c, 12, 16.

F.E.

Received by Chief Ship Surveyor 9.12.18

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "WAR HAVEN". Rpt. Nwe. No. 71458

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 72. Depth "d" 21.75.

Framing: Table No. 3 page Description Bulb angle as approved.

Longitudinal No. 23832

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.03.$

Bridge Deck Sheerstrake as approved.

Downton pump and kedge anchor dispensed with as in Standard Vessels.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100 A.1. (Steel) as recommended.

1 Deck (Steel).

Cell D.B. 284. 734t. F.P.T. 110t. A.P.T. 128t.

F.K. 7 B.H. pt.Cem. Lloyd's A. & C.P. P.33', B.98', F.29',

M

9. 12. 18.

The Certificate of Classification, with endorsement "Our plans are not fitted" and the same should be posted in the Register Book.

The plans received with report. A missing section should be requested for the preparation of Certificate.

015039-015063-0320



© 2021 Lloyd's Register Foundation