

Action is Deferred for S.S. (postponement until 12.53 app.)
 Subsequent post. until 5.54 approved provided a further satisfactory
 G.E. is held.

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME

Jane Lanning

REPORT

Liv.

No.

138692

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey Deck, A.S. + G.E. as above

When due

5.53.

noted

Subject to permanent repairs to shell plating in
 way of E.R. (S.S.) also in way of fore peak lower space (S.S.),
 to coaming plate of E.R. aft bulkhead, upper deck plating
 and inner surface of shell plating generally in holds
 and E.R. being specially examined for (pitting)
 by next Special Survey.

Action is Deferred for S.S. by 5.54.

End. of class (B).

Indented side shell plating (S.S.).



© 2021

Lloyd's Register
 Foundation

015054-015062-0084

General Observations, Opinion as to Class, Recommendation, &c.: