

COPY.

Lloyd's Register of Shipping.



Port of NANTES

11th February 1927

This is to Certify that

----- P.W. WEBSTER -----
the undersigned Surveyor to this Society did at the request of the Owners Representative, and consent of Builders, survey the Twin Screw Steamer "ITAMBE" building at Chantier & Ateliers de Saint-Nazaire, Penhoët, on 4th February and subsequent dates, afloat and in dry dock for the purpose of ascertaining the nature and extent of damage stated to have been sustained by dropping load during test of heavy derrick on 4th February 1927.

FOUND

RECOMMENDED

No.3 plate Starboard side in and below upper sheer sharply indented and fractured.

To be renewed.

Stringer bar in way buckled.

To be renewed.

The Foregoing recommendations are made with a view to restore the vessel to the same condition to which she was in before the casualty occurred.

All new and disturbed work to be finished and coated, to be left in a similar condition to other parts of vessel.

P. W. Webster

Surveyor to LLOYD'S REGISTER

OF SHIPPING - CHARTERS -

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:--
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

015102-015110-0078

Lloyd's Register
Foundation