

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 3551 (6 Lines)

27th February, 1953.

Dear Sirs,

Steamer "T.W.I."

With reference to the previous correspondence respecting the case of the above-named ship, I have to inform you that information has been received to the effect that the vessel has resumed service without the repairs which were recommended by the Society's Surveyors at their survey in May/October 1952 being carried out.

In these circumstances, the Committee at their meeting to-day gave instructions for the class to be expunged from the Register Book with a Black Line indicating withdrawal of class on account of reported defects.

Yours faithfully,

c. c. Lon.

Clerk to the  
Classification Committee.

The Thames Welding Co., Ltd.,  
Orchard Dock House,  
7, Bevis Marks,  
LONDON, E.C. 3.



© 2021

Lloyd's Register  
Foundation

015155-016162-0014