

1E

Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

E

*Morivoli*

Rpt.

*Indl. No. 15491*

No. *15492*

*W.L. 17482*

the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also setting out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points entered in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Engine

*Trip Expansion*

Boilers fitted with forced draught

Oil Shaft. If fitted with a continuous liner

If fitted with an outside gland of }  
approved type

*No*  
*Yes*  
*No*

his vessel's machinery appears to have been built in accordance  
the Rules and the approved plans, and it is submitted she is  
able to be classed *+LMC 9.35.*

*L.H.*  
*18/9/35.*



© 2021

Lloyd's Register  
Foundation

015155-015162-0134