

Ship's name

EMPIRE SAM

Port

H.KG

No.

18154

Class is subject to

NIK

Last survey date


3-12-63

6 - JAN 1964

Readjustment of main boiler safety valves
under steam due to valves having been
inadvertently opened up at routine overhaul of
machinery.

It is submitted that this
vessel is fit to remain
as CLASSED.

G.T.A.



20-12-63

© 2021

Lloyd's Register
Foundation