

[Thin Copy for attaching to Report.]

4a.

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port of H U L L.

28th August, 1953.


Dear Sirs,

With reference to the Survey now being held on the ~~Steamer~~ Motor vessel "DRAKELOW",

I beg to inform you that, in consequence of the condition of this vessel's Port generator set crank case,

it will be my duty to recommend to the Committee that the same be repaired & examined, before the end of FEBRUARY, 1953, as provided for in the Rules, an extract from which appears on the other side:—the continuance of the vessel's character in the Society's Register Book to be subject to the due fulfilment of this condition.

Yours faithfully,


Engineer Surveyor to Lloyd's Register.

The Drakelow S.S. Co., Ltd.,

CARDIFF.

Lloyd's Register
Foundation

015224-015232-0328