

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.



Port: No. ...
...ed in at Head

AMERICAN TRADING & SHIPPING CO. PTY. LTD.

TELEPHONE: BU 4147
(3 LINES)

SHIPPING & CHARTERING BROKERS

AGENCIES IN ALL AUSTRALIAN AND N.Z. PORTS

TELEGRAPHIC AND CABLE ADDRESS: "AMTRACO"

IMPORT — EXPORT
GENERAL MERCHANDISE

ALSO
NEW YORK
SAN FRANCISCO
VANCOUVER, B.C.
LONDON

DAVID BRUCE & CO., LONDON
SALVAGE ASSN. INC. NEW YORK
AMERICAN TRADING CO., INC. NEW YORK
MESFARMERS' LINE
ROLLERS' LTD., HONGKONG AND LONDON
PACIFIC SHIPOWNERS LTD., SUVA
C. SHIP CHARTERING CO. LTD. VANCOUVER

BOX 49, G.P.O., SYDNEY
SCOTTISH HOUSE, 17-19 BRIDGE STREET,
SYDNEY, 8th January 1958

Messrs. Lloyd's Register of Shipping.,
4, Bridge Street,
SYDNEY...N.S.W.

Dear Sirs,

Re:- "AI SOKULA".

Kindly note that the Owners of the above vessel have advised us of their decision to allow Lloyd's classification of the above vessel to lapse as from the date of expiry of her present certificates during December 1957 / January 1958.

Owners have further asked us to inform you of this decision so that the necessary information may be transmitted to Lloyd's of London.

The vessel is only trading in Fijian waters, which necessitates full certificates from the Fijian Marine Board, which to a great extent is a duplication of Lloyd's certificates, and to keep both certificates current only means a duplication of surveys.

As it is not intended that the vessel should extend her trade in any way, it appears to the Owners that the Fijian Marine Board certificates are adequate for their requirements.

The vessel is presently trading under certificates issued by the Board expiring on the 31st March 1958, when she will then undergo a further full Marine Board survey.

Yours faithfully,

AS AGENTS.

RNSM/EGC.



© 2021

Lloyd's Register Foundation

015390 - 015404 - 0228