

2 SEP 1953

"SIDI BELYOUT"

Before this case receives consideration, IT IS SUBMITTED  
the Surveyors appointed by Lloyd's Agents at Casablanca be  
requested to confirm that the safety valves were adjusted  
to 180 lb. per sq. inch <sup>instead of the normal working pressure of 230 lb.</sup> at the Owners' request; further that  
the oil fuel and fire extinguishing installations have been  
examined under working conditions. ~~at this time.~~

*Mr. 16/9/53*

*X*  
*19*

*WJ*  
31.8.53.

*7-8*



© 2021

Lloyd's Register  
Foundation

015390 - 015404 - 0371

0-45 F

invol(s)....  
nder stea  
nder stea  
Boilers ?  
Boilers ?  
Boilers ?  
ice fitted  
Has it a  
itchgear  
ry Spa