

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office)

TUES. 10 OCT 1893

No. 4658

Date of writing Report Oct 9 1893 When handed in at Local Office Oct 9 1893 Port of Aberdeen

No. in Reg. Book.	Survey held at Aberdeen	Date, First Survey Oct 7 1893 (No. of Visits)	Last Survey Oct 4 1893
48	on the Wood, Iron or Steel P. S. James Hall	Master Mr. Donald	YEAR MONTH
TONNAGE:-	Built at Aberdeen	By whom Hall Russell & Co. When 1890 4 ✓	
GROSS 366	Owners Alex Loh & Murray Firth & S. Co. Ltd.	Port belonging to Aberdeen	
UNDER Dk. 314	Owners' Address	(if not already recorded in Appendix to Register Book.)	
NET 196	Surveyed Afloat or in Dry Dock? dry dock Name of Dock Alva dry dock	Destined Voyage coasting	
WB=DA	tons; f tons; E&B tons; Cell DB tons;	tons; f tons; APT tons; MT tons.	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
FPT			CHARACTER For Special Survey. Date of last Survey and of Periodical Surveys.

N.B. - All alterations in the existing records should be underlined.

Last Survey, No. 7104 Port Hh

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Damage Survey

CHARACTER For Special Survey. Date of last Survey and of Periodical Surveys.	Years Assured now expired.	Machinery and Boiler & Surveys (including date of N.B., if any).
190 A 1 12.92	190 to 12.92	
C. Alva No. 3 12.92	191 to 12.92	
Alva No. 2, 92		

Society's Freeboard (if assigned) as painted on Ship and now verified

1 ft. 11 1/2 ins.
additional free
port to be cut.

This vessel having been ashore on the 6th instant at Anstruther. She has been placed in the above dry dock and the bottom examined. The 3rd & 4th plates from the stem in A strake; the 2nd & 3rd plates in B strake and the adjoining plate in C strake on the starboard side indented one plate in A strake, and the landing of B strake amidships also indented up to lid. Three rivets in the shoe of the garboard plate aft with heads gone and a few pudder rivets slack. Owing to the cargo being in the holds the repairs could not be effected. The owner proposes to dock the vessel next month, when she is due for her Board of Trade Survey, and have the above damage made good.

SUMMARY OF DAMAGE REPAIRS:— Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs

PRESENT CONDITION OF THE

Decks	Good	Transoms, Pointers, & Crutches	Timbered	Copper, or Y.M.	Hatches
Waterways	.	Timbers of Frame at the openings	.	(State if on Felt.)	Boats
Coamings	.	Ditto ditto at other places	.	When put on, Month Year	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Not Seen	Keelsons	.	Rudder	Condition, how ascertained from the
Low'r Dk. Beams & Fastenings	.	Clamps, Shelfs & Stringers	.	Windlass & Capstan	Sails
Plating	To be repaired	Salting	(State if examined.)	Pumps	Equipment letter
Planking	.	Ceiling	.	Engine Room Skylights	Anchors, No. of
Treenails or Rivets	.	Cement on Asphalt	To be examined (State which.)	Coal Bunker, Open'gs, Lids, &c.	13 18 18 9 ✓
Breasthooks & Stemson	Not Seen	Tanks	(State if now tested.)	Scuppers	Cables (State if now ranged.)
			Caulking of Bot'm, Dk, & Wat'r'ys	Cargo & Main Hatch'ys	" length 16.5 fath size 1 to
					" Rule length 16.5 " size 1 to
					Hawsers & Warps
					Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 991," or "to remain as classed and to have record of survey, 991, and the notations of 'No. 1-91 and ptND91, &c.'"

The damage sustained does not in my opinion affect the seaworthiness of the vessel, but in order to retain her character in the Register Bk I would respectfully recommend that the vessel be again placed in dry dock; the ceiling in way of the damage to be lifted, and the plates to be taken off & fair'd.

Office Fee (if chargeable) per Scale II, Sec. 27 £ : : :

Fees applied for,

Survey Fee (per Section 28) £ : : :

18.

Special Damage or Repair Fee (if any) £ : : :

Received by me,

Travelling Expenses (if chargeable) £ : : :

18.

Second Surveyor's Fee (if any) £ : : :

* Is Certificate now required?

Committee's Minute

Character assigned Deferred for repair

d.

FRI 13 OCT 1893

Surveyor to Lloyd's Register of British & Foreign Shipping.

FRI 2 FEB 1894

FRI 8 DEC 1893

© 2019
Deferred
Lloyd's Register
Foundation

ADM-0285